

PETROSH'S



BIG TOP

All Occasion Party Rentals

455 Philadelphia Ave.

Egg Harbor City, NJ 08215

Voice 609-804-9805

Fax 609-804-9810

e-mail steve@petrosh-bigtop

www.petrosh-bigtop.com

6 Easy Steps to Pop the Best Popcorn:

1. Turn all switches "ON"
 2. For first batch only, let kettle heat about 4 minutes.
 3. Add contents of one packet of oil and popcorn.
 4. Dump when popping is about 99% completed.
 5. Repeat steps 3 & 4 - always pop at least 5 batches each time you pop.
 6. On final batch only, turn the Kettle Heat Switch OFF as soon as corn starts popping rapidly (to raise kettle lid)
- WARNING!** Keep Kettle Switch "OFF" when not popping

KEEP MOTOR & HEAT SWITCH "OFF" WHEN NOT
POPPING CORN.

KEEP DOORS OPEN WHEN POPPING CORN.

KEEP DOORS CLOSED WHEN YOU ARE NOT POPPING
CORN.